

XRAY NTH



2-SPEED SHAFT WEAR INSPECTION

We recommended that you frequently check the 2-speed shaft (#335510) for excessive wear. When the 2-speed shaft is worn, the one-way bearing can stack and this can cause teeth to break on the spur gear. Therefore, when the 2-speed shaft is excessively worn, you should exchange it for a new one.



If you have any questions, please do not hesitate to contact XRAY at info@teamxray.com or visit our website at www.teamxray.com for news and updates.