




## #382500 MICRO SERVO SAVER



### When Using With XRAY M18:

When using stock 12° front upper arms, the servo saver may touch the steering block when the wheels are turned. We suggest removing a small amount of material from the steering block as shown. This issue does not occur when using the optional 6° front upper arms.

